

Oil Field Environmental Incident Summary

Incident: 20150309124609 **Date/Time of Notice:** 03/09/2015 12:46
Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC
Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC
Well Name: BRADLEY 44-7H
Field Name: CARTER **Well File #:** 14726
Date Incident: 3/9/2015 **Time Incident:** 10:40 **Facility ID Number:**
County: BURKE **Twp:** 162 **Rng:** 89 **Sec:** 7 **Qtr:**
Location Description:

Submitted By: Gary Watson **Received By:**
Contact Person: Mark Bonnie
103 First Avenue NE
Mohall, ND 58761

General Land Use: Cultivated **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident Pipeline Leak

Release Contained in Dike Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.5	Barrels		
Brine	3.5	Barrels	3.5	Barrels		

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

Minimal impact to well site soil.

Areal Extent:

Potential Environmental Impacts:

Minimal impact to wellsite soil.

Action Taken or Planned:

Jim Potts (NDIC Inspector) has been notified. The released fluids will be vacuumed-up and the affected facility soil will be scraped-up, collected and hauled to an approved disposal facility.

Wastes Disposal Location: Approved disposal facility.

Agencies Involved:

Updates

Date: 3/9/2015

Status: Reviewed; O&G Lead

Staff: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.